CITY OF BALTIMORE WET W SMOKE AND DYED W	Page 1 of 3	
Sewershed: JONES FALLS SEWERSHED	Company: REI/DRAYCO	Date: 05/05/2008
Test to be Performed: SMOKE	Ground Condition: DRY	Supervisor: ER
Manhole ID: S39CC1023MH	Test ID: S994-308	Notifications Made:_X_ (Residents, Fire, 311)

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



CITY OF BALTIMORE WET WE SMOKE AND DYED WA							Page 2 of 3			
Sewershed: _JONES FALLS			Compan	y:RE	I/DRAYCO	Date: 05-05-2008				
Test to be Performed:			Ground Condition:				Supervisor: E.R.			
Smoke:X Dyed Water:			Dry:X	(Dar	mp: W					
Manhole ID:S39CC1023MH					0994-308	Notifications Made:X (Residents, Fire, 311)				
Field Sketch: (Show all Manholes with Numbers Locations, Street Names, Building Addresses and					•					
Defect				Source			Drainage		Photo	
No.		Address		Type	Location	Sector	Area	Severity	Number	
1	750 MELVILLE	AVE.		03	07	02	6	03	308-OB01-01	
2	751 36TH ST.			03	07	02	6	03	308-OB02-01	
				OBSERV	/ATION	CODES				
	Source Type	Location	Sector	Severity	ATION	Source Type	Location			
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame Seal	Non-Paved			
	Service Line	Paved Asphalt	Private	Trace		Storm Drain	Field/Woods			
	Cleanout	Paved Other	1 IIVale	Moderate		Catch Basin/Inlet				
	Downspout	Driveway		Major		Storm Manhole	Golf Course			
	Area Drain	Sidewalk		ινιαμΟι		Storm Ditch	Other			
	Driveway Drain	Curb				Excavation	Jui 101			
	Stairwell Drain	Yard- Front				Other				
	Foundation Drain	Yard-Back			10					
	Building Interior	Yard- Side								

CITY OF BALTIMORE WET WE SMOKE AND DYED WA	Page 3 of 3	
Sewershed: JONES FALLS SEWERSHED	Company: REI/DRAYCO	Date: 05/05/08
Test to be Performed:	Ground Condition:	Supervisor: ER
Smoke:X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: S39CC1023MH	Test ID:0994-308	Notifications Made:X (Residents, Fire, 311)



0994-308_OB01-01.jpg



0994-308_OB02-01.jpg